

---

**Software Name:** Firmware for EDR-810 Series

---

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
-------------	------------------------------	--------------	-----------------	----------------------------	--------------------	------

## Software Name: Firmware for EDR-810 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
5.0	N/A	null	N/A	<b>New Features:</b> <ol style="list-style-type: none"> <li>1. Support 12 digits serial number in EDR-810 HW revision v2.0.0</li> <li>2. Support VPN and VRRP LED in EDR-810 HW revision v2.0.0</li> <li>3. MIB ifadminstatus supports port setting.</li> </ol> <b>Enhancements:</b> <ol style="list-style-type: none"> <li>1. Support default reoute in "Static Route" function.</li> <li>2. Support "STP Topology Changed" in Event log.</li> <li>3. Support "RSTP Topology Changed" notification in System Event Setting.</li> <li>4. Upgrade to OPENSSL v1.0.2 package.</li> <li>5. System reboot when out-of-memory is detected.</li> <li>6. Support service port setting in Modbus firewall.</li> <li>7. Show error message to remind wrong old password.</li> <li>8. Time zone formate of exported event log.</li> <li>9. Add RSTP path cost setting check mechanism.</li> </ol>	<b>Bugs Fixed:</b> <ol style="list-style-type: none"> <li>1. Fix CVE-2015-0235, CVE-2018-16282.</li> <li>2. Fix XSS attack vulnerability.</li> <li>3. Switching function failure but serial console is workable.</li> <li>4. System information isn't sync in real time with Syslog event.</li> <li>5. "Keep certificate" function isn't supported in model EDR-810-2GSFP and</li> <li>6. EDR-810-2GSFP-T.</li> <li>7. EventlogEntry has conflicting syntax after compiling MIB.</li> <li>8. When system reboot, system will send Turbo ring v2 topology change event log.</li> <li>9. Gibberish shown in Web GUI.</li> <li>10. DHCP and NAT setting through Quick Stting Profile isn't valid.</li> <li>11. Packet loop caused by trunk port link off and link on.</li> <li>12. After importing configuration file, trunk port will shut down.</li> <li>13. Packet counter statics can't show fiber interface packet amount information.</li> <li>14. User can't use MIB file to read event log.</li> <li>15. RSTP configuration import failure.</li> <li>16. Unstable network connection caused by the same virtual IP and interface IP.</li> <li>17. Bandwidth Utilization" display mode always show 0%</li> <li>18. In Web GUI and CLI, the display of RSTP edge port status isn't sync.</li> <li>19. User can't get ring master MAC address through MIB file.</li> <li>20. Abnormal VRRP behavior due to VRRP virtual IP isn't updated in routing table</li> <li>21. System looping caused by bridge priority change</li> <li>22. Low RSTP convergence speed.</li> <li>23. There is possibility that VRRP can't work normally with VLAN ID over 15.</li> <li>24. VRRP setting isn't sync with VLAN setting.</li> <li>25. With RSTP enable, there is possibility that system looping will happen when system has link on/off or reboot.</li> <li>26. After trunk port disabling, MAC address table won't</li> </ol>	N/A

## Software Name: Firmware for EDR-810 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
					<p>sync up.</p> <p>27. Turbo Ring function won't be disabled after RSTP configuration is imported.</p> <p>28. When using link-off port to set VRRP, the VRRP status shows master other than init.</p> <p>29. LLDP port event won't update in real time when port link down.</p> <p>30. CLI can't disable tracking interface of VRRP.</p> <p>31. Network interface of VRRP doesn't sync with VLAN interface setting.</p> <p>32. Export configuration file after removing WAN interface. And then use this configuration file to import in the system, but system shows MTU configuration import failure.</p> <p>33. Firewall blacklist can't support Modbus function code 5, 6, 8, 21, 22.</p> <p>34. Firewall rule with master query and slave response in Modbus function code 20 are invalid.</p> <p><b>Changes:</b></p> <p>1. Rename RSTP "Port Cost" parameter to "Path Cost".</p>	