

Software Name: Firmware for NPort 5600-DT Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v2.6	Build 19032122	N/A	NPort 5600-DT Series	<p>New Features:</p> <ol style="list-style-type: none"> 1. Supports HTTPS. 2. Supports MXview auto-topology function. 3. Supports MXconfig. 4. Supports SNMPv2c. 5. Supports IGMP. 6. Supports new flash because of component end-of-life. <p>Enhancements:</p> <ol style="list-style-type: none"> 1. Accessible IP list can now be used to restrict all device services. 2. Complies with Moxa Security Guidelines on the following: Account Authentication Management, Network Service Management, and Audit and Log Management. 3. CVE-2017-14028: An attacker may be able to exhaust memory resources by sending a large amount of TCP SYN packets. 4. CVE-2017-16715: An attacker may be able to exploit a flaw in the handling of Ethernet frame padding that may allow for information exposure. 5. CVE-2017-16719: An attacker may be able to inject packets that could potentially disrupt the availability of the device. 6. Updates the web UI. 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. NPort does not send SNMP Authentication Failure trap. 2. Pair connection mode cannot resolve the domain name. <p>Changes:</p> <p>N/A</p>	N/A
v2.5	Build 17030709	N/A	NPort 5610-8-DT, NPort 5610-8-DT-J, NPort 5650-8-DT, NPort 5650I-8-DT, NPort 5650-8-DT-J	<p>New Features:</p> <p>N/A</p> <p>Enhancements:</p> <p>N/A</p>	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. The user's password and SNMP community name may be exposed by a buffer overflow issue. <p>Changes:</p> <p>N/A</p>	N/A

Software Name: Firmware for NPort 5600-DT Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v2.4	Build 16100514	N/A	NPort 5610-8-DT, NPort 5610-8-DT-J, NPort 5650-8-DT, NPort 5650I-8-DT, NPort 5650-8-DT-J	<p>New Features: N/A</p> <p>Enhancements:</p> <ol style="list-style-type: none"> Enhanced web login security and supports 5 users logged in simultaneously. Extended HTTP challenge ID length from 32 bits to 256 bits. Enabled the default password "moxa". Increased CSRF protection mechanism. Increased XSS protection mechanism. The IP address of the NPort can be set to an address ending with 0 or 255. Supports "ARP probe" in RFC5227. NPort would respond for ARP requests with sender IP address 0.0.0.0. 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> NPort cannot send e-mail using Google's SMTP server. In pair connection mode, master does not pull down RTS/DTR signal after the TCP connection is broken. Command port sends lots of "D_ASPP_CMD_ALIVE" packets after running for 50 days. NPort may reboot or hang from several buffer overflow attacks through Telnet, SSH, DSCI, SNMP, HTTP, and HTTPS. <p>Changes: N/A</p>	N/A

Software Name: Firmware for NPort 5600-DT Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v2.3	Build 15041515	N/A	NPort 5610-8-DT, NPort 5610-8-DT-J, NPort 5650-8-DT, NPort 5650I-8-DT, NPort 5650-8-DT-J	<p>New Features: N/A</p> <p>Enhancements:</p> <ol style="list-style-type: none"> 1. Uses model name instead of "NULL" for SNMP object "sysDescr". 2. Supports connecting to the server by domain name and the server IP will change dynamically. 3. Supports updating the ARP table by gratuitous ARP. 4. Supports time synchronization with an NTPv4 server. 5. Supports RFC2217 NOTIFY-LINESTATE for Transfer Shift Register Empty and Transfer Holding Register Empty. 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. If an SNMP GETNEXT command is issued on an object that does not exist, 'no such name error' is displayed. 2. When DHCP renews IPs, if the IP was originally given by a relay agent, NPort should send a DHCP request to the relay agent, not the DHCP server. 3. In Real COM mode, when the modem status of the NPort's serial port is changed frequently, the NPort will sometimes fail to notify the change to the driver. 4. In reverse telnet mode, the NPort will try to subnegotiate the COM port control options without option negotiation first. 5. In RFC2217 Mode, if the Ethernet data has many FF characters, some data may be lost while passing the data to the serial side. 6. The telnet console and serial console sometimes do not work. <p>Changes: N/A</p>	N/A