



## Firmware for NPort W2150A/W2250A Series Release Notes

<b>Version: v2.2</b>	<b>Build: Build 18082311</b>
<b>Release Date: Jan 15, 2019</b>	

### Applicable Products

NPort W2150A, NPort W2150A-T, NPort W2250A, NPort W2250A-T

### Supported Operating Systems

N/A

### New Features

N/A

### Enhancements

- Improved the fast roaming algorithm.
- In Real COM and TCP server mode, connection will be reset when the connection number has already reached the "max connection number".
- Reduced TCP retransmission timeout based on "TCP alive check time".
- Prevents wireless connections from reconnecting frequently.
- Prevents XSS attacks on webpage.
- Prevents CSRF attacks on webpage.
- Prevents potential command injection on webpage.
- Enhanced client authentication on web login page.
- Removed the wording below the goahead logo.

### Bugs Fixed

- When fast roaming is enabled, NPort may roam to a non-selected channel.
- Goahead vulnerability(CVE-2017-17562), which caused the webpage to crash.
- Buffer overflow issue on TCP port 4900.

### Changes

N/A

### Notes

N/A



<b>Version: v2.1</b>	<b>Build: Build 17112017</b>
<b>Release Date: N/A</b>	

### **Applicable Products**

NPort W2150A, NPort W2150A-T, NPort W2250A, NPort W2250A-T

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

N/A

### **Bugs Fixed**

- WPA2 KRACK vulnerabilities which are associated with the following CVE identifiers: CVE-2017-13077, CVE-2017-13078, CVE-2017-13079, CVE-2017-13080, CVE-2017-13081, CVE-2017-13082, CVE-2017-13084, CVE-2017-13086, CVE-2017-13087, and CVE-2017-13088.
- W2x50A can connect to some APs that are using 802.11n, but cannot launch a web or telnet console.

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v2.0</b>	<b>Build: Build 17081115</b>
<b>Release Date: N/A</b>	

**Applicable Products**

NPort W2150A, NPort W2150A-T, NPort W2250A, NPort W2250A-T

**Supported Operating Systems**

N/A

**New Features**

- Modified firmware structure for security purposes; please upgrade to v1.11 before upgrading to v2.0.

**Enhancements**

- Supports new architecture of NPort W2x50A firmware.

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A



<b>Version: v1.11</b>	<b>Build: Build 17081115</b>
<b>Release Date: N/A</b>	

### **Applicable Products**

NPort W2150A, NPort W2150A-T, NPort W2250A, NPort W2250A-T

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

- Supports accepting encrypted firmware for v2.0 and above.
- Added a default password.
- Improved the wireless stability when signal strength is low.
- Upgraded openssl to openssl-1.0.2k.
- Upgraded dropbear SSH to dropbear-2016.74.

### **Bugs Fixed**

- When fast roaming is enabled and the wireless signal is better than the roaming threshold for a long time, sometimes data may not be able to be sent out.
- WLAN could not pass RADIUS authentication when security is set to EAP-TLS.
- When bridge mode is enabled, NPort may not function properly after receiving PROFINET packets.

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.10</b>	<b>Build: Build 16113018</b>
<b>Release Date: N/A</b>	

### **Applicable Products**

NPort W2150A, NPort W2150A-T, NPort W2250A, NPort W2250A-T

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

- Supports 802.11n in Infrastructure mode.
- Supports W2X50A-CN.
- Supports WLAN log.
- Supports new site survey on general profile setting page.
- Shows RSSI and current BSSID on WLAN status page.
- Upgraded glibc to v2.18.
- Modified the fast roaming mechanism, which is triggered by low signal (RSSI).
- Removed password related items from snmp.
- Supports import/export by DSU.

### **Bugs Fixed**

- The "Connection goes down" function may not work correctly in Real COM mode for W2250A Port 2 .
- Sometimes the device may not be able to establish a wireless connection after booting up.
- W2x50A may not be able to connect to any APs for a long time, and sometimes it cannot recover.
- When fast roaming is enabled and the wireless signal is unstable for a long time, sometimes data may not be able to be sent out.
- When Ethernet bridge is enabled, sometimes data may not be able to be sent out.
- When Ethernet bridge is enabled, IP conflict checks may not work on the WLAN side.
- Ready LED may not blink red when IP conflicts are detected.
- The local time may not be correct when changing the time zone setting.
- GHOST vulnerability: ICS-CERT CVE-2015-0235.
- DROWN attack issue: ICS-CERT CVE-2016-0800.

### **Changes**

N/A

### **Notes**

N/A