



Firmware for TAP-323 Series Release Notes

Version: v1.8	Build: 21080414
Release Date: Nov 30, 2021	

Applicable Products

TAP-323 series

Supported Operating Systems

N/A

New Features

- Added support for the remote diagnostics feature on the Troubleshooting page.
- Added a Clear Log option to the Maintenance page.
- Added support for AAA authentication.
- Added support for Moxa Wireless Protect.
- Added Login/Authentication Failure Message settings in System Information.
- Added the Management Frame Encryption Password setting in Basic WLAN Setup.
- Added additional Multicast rate options for Advanced Wireless Settings.
- Added the option to enable or disable CCA.
- Added a client-to-AP retry count (1-4) option to Advanced Wireless Settings.
- Added support for a bidirectional Keep Alive mechanism for controller-based roaming.
- Added a bi-directional Keep Alive Check option.
- Added Alive Check interval and count settings.
- Added Turbo roaming events to System Log Event Types and Syslog Event Types.
- Added Coordinator Status events to Notification Event Types and Trap Event Types.
- Added Coordinator Status events to Relay Event Types
- Added the SMTP Port and SMTP Security Mode options to E-mail Server Settings.
- Added the Outgoing Packets and Incoming Packet status to Wireless LAN Status.
- Added an Export Log button to the DHCP Client List page.
- Added a page range to System Logs.
- Added the System, Account, ARP, Bridge, and LLDP Status to Status
- Added the Accessible Net List to the console.
- Added the Auto Logout period setting to the console.
- Added an encryption option for the Configuration Import & Export function.
- Added HTTP/HTTPS/Telnet/SSH, and SNMP settings to LAN and WLAN Settings.

Enhancements

- Cybersecurity enhancements.
- Adjusted the accuracy of the transmission (tx) rate to the second decimal.
- Enhanced the group check logic for WLAN, 50 ms roaming, security mode, and WAC settings.
- Network information (including IP, subnet mask, and gateway) has been added to the “Reboot” and “Save Configuration and Restart” pages to show the expected network settings after performing these tasks.
- The same SSID can now be used on both WLAN interfaces.

Bugs Fixed

- The certificate authentication is sometimes rejected by the server.
- The web server may sometimes crash due to a memory leak.
- Incorrect language on the Turbo Chain Status page.
- The real-time-clock (RTC) does not work if the system is not powered on for a long time.



Changes

- Changed the RF type default value from “B/G/N Mixed” to “2.4G N”. Wireless.
- Changed the Wireless default state on the Operation Mode page from “enabled” to “disabled”.
- Changed the default value of the Client lease time for the DHCP server from 5 days to 14400 min.
- Changed the default MAC Filters policy from “accept” to “drop”.
- Changed the default state of HTTP and Telnet on the Console Settings page from “enabled” to “disabled”.
- Removed the ability to press Enter to trigger the ping function.

Notes

N/A



Version: v1.3	Build: N/A
Release Date: Mar 21, 2018	

Applicable Products

N/A

Supported Operating Systems

Linux 2.6.x

New Features

First release

Enhancements

First release

Bugs Fixed

First release

Changes

First release

Notes

First release