



Firmware for EDS-405A Series Release Notes

Version: v3.8	Build: Build_17051216
Release Date: Jun 29, 2017	

Applicable Products

EDS-405A-T, EDS-405A-EIP, EDS-405A, EDS-405A-MM-SC, EDS-405A-MM-ST, EDS-405A-SS-SC-T, EDS-405A-MM-SC-T, EDS-405A-SS-SC, EDS-405A-EIP-T, EDS-405A-MM-ST-T

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- User account login authentication error in menu console mode.

Changes

N/A

Notes

N/A



Version: v3.7	Build: Build_17031513
Release Date: N/A	

Applicable Products

EDS-405A Series

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- Added warning message when default password was not changed.
- Encrypted security keys in user interface.

Bugs Fixed

- Cross-site scripting vulnerability.
- Denial of Service attack vulnerability.
- Privilege escalation vulnerability.
- SSL v2/v3 vulnerability in https.
- Web console cannot be accessed due to SNMP get bulk.
- Specific CLI command caused the switch to reboot with default settings.
- Added a new VLAN will change IGMP querier state from disable to enable.
- Saving configuration to ABC-01 cannot be performed via IE browser.
- Rate limit cannot be set in web UI.
- Corrected RSTP edge definition in exported configuration file.
- Corrected authorization of Radius/TACACS+ login.
- Corrected RSTP Auto-Edge behavior.
- Web console is inaccessible after changing VLAN setting.
- Configure LLDP via MXconfig cause SNMP module hangs.
- Cannot set password via MXconfig.

Changes

N/A

Notes

N/A



Version: v3.6	Build: Build_15080712
Release Date: N/A	

Applicable Products

EDS-405A Series

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- Turbo Ring/Turbo Chain operate unstably after the switch performs a warm start.
- RSTP function was incompatible with some third party devices.
- Switch configuration export error via CLI.
- Switch packet counter information error via SNMP polling.
- Web user interface Diagnosis > Ping page is vulnerable to XSS attack.
- Switch may reboot when using special URL to attack web user interface.
- User account privileges can be changed by Firefox browser web developer plugin.

Changes

N/A

Notes

N/A



Version: v3.5	Build: Build_14121009
Release Date: N/A	

Applicable Products

EDS-405A Series

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- Web user interface display errors under Java 8 environments

Changes

N/A

Notes

N/A



Version: v3.4	Build: N/A
Release Date: N/A	

Applicable Products

EDS-405A Series

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- Switch rebooted when port-based VLAN is enabled.
- Network looping when IPv6 based computer connects to Turbo Ring or Turbo Chain network.
- Traffic rate limiting setting errors when switching between Normal mode and Port Disable mode.
- IGMP snooping operated incorrectly when IGMP control messages were not with PVID 1.
- Static multicast setting errors when changing VLAN settings.
- Configuration import/export errors in CLI mode.

Changes

N/A

Notes

N/A



Version: v3.3	Build: Build_13070416
Release Date: Jul 09, 2013	

Applicable Products

EDS-405A Series

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- Added a web interface for loop protection enable/disable.
- Added a web interface for SSH/SSL key generation.
- Added SNMP MIB for SFP DDM (Diagnostics).

Bugs Fixed

- Log in failed in the CLI mode when the password contained a special character.
- Hybrid VLAN lacked the SNMP MIB object.
- SFP DDM (Diagnostics) displayed inaccurate values.
- IEEE 1588 PTP did not function correctly.

Changes

N/A

Notes

N/A



Version: v3.1	Build: N/A
Release Date: N/A	

Applicable Products

EDS-405A Series

Supported Operating Systems

N/A

New Features

- Users can disable “Utility Search”, “Telnet Console”, “SSH Console”, “HTTP Console”, and “HTTPS Console”, or change the service ports of the above consoles.
- Supports up to 10 user-defined login accounts for consoles.

Enhancements

- Passed ODVA EtherNet/IP certificate.
- Added some minor SNMP OIDs.
- Enhanced multicast performance.
- Added version number in MIB file.

Bugs Fixed

- NTP cannot synchronize time in default setting.
- NTP client function cannot work with Windows XP NTP server.
- Firmware upgrade failed when IEEE 802.1x was enabled.
- Switch reboots when receiving IGMP v3 packets (commonly used in Windows 7).

Changes

N/A

Notes

N/A



Version: v3.0	Build: N/A
Release Date: N/A	

Applicable Products

EDS-405A Series

Supported Operating Systems

N/A

New Features

- RSTP-2004.
- NTP Server/Client.
- Hybrid VLAN.
- Command Line Interface.
- EtherNet/IP.
- Egress rate limit.
- Unknown unicast filtering.
- CPU loading monitoring.
- Change IP without reboot.
- DHCP Discover retry configuration.
- GARP timer adjustment.
- Loop-protection.
- Link Fault Shutdown (Disable mode in "Rate Limit" function).

Enhancements

N/A

Bugs Fixed

- IGMP snooping chip issue problem.

Changes

- Changed default password to "moxa".

Notes

N/A



Version: v2.7	Build: N/A
Release Date: N/A	

Applicable Products

EDS-405A Series

Supported Operating Systems

N/A

New Features

- Added IGMP Snooping function.
- Added IEEE 802.1Q VLAN function.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A



Version: v2.6	Build: N/A
Release Date: Dec 24, 2009	

Applicable Products

EDS-405A, EDS-405A-MM-ST, EDS-405A-MM-SC, EDS-405A-SS-SC, EDS-405A-T, EDS-405A-SS-SC-T, EDS-405A-EIP, EDS-405A-EIP-T, EDS-405A-MM-SC-T, EDS-405A-MM-ST-T

Supported Operating Systems

N/A

New Features

- 1. Supports TurboPack™ 2009 (Add the new managed functions of Turbo Chain, IPv6, Modbus/TCP, IEEE 1588 PTP, SNMP Inform, LLDP, DHCP Option 82, Firefox, and SSH)
- Add new Turbo Ring (Turbo Ring V2) Function
- Add new Ring Coupling Function
- Add Daylight Saving Function

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

For products with firmware prior to v2.6, users must upgrade to v2.6 before upgrading to the latest v3.X firmware.



Version: v1.3	Build: N/A
Release Date: N/A	

Applicable Products

EDS-405A Series

Supported Operating Systems

N/A

New Features

- Added Syslog function.
- Added Restart function.
- ABC-01 supported.
- Change default settings of Flow Control from Enabled to Disabled.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A



Version: v1.1	Build: N/A
Release Date: N/A	

Applicable Products

EDS-405A Series

Supported Operating Systems

N/A

New Features

- First release for EDS-405A Series.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A