



Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
3.8	N/A	N/A	PT-508 series	Enhancements: 1. Add warning message when default password was not changed 2. Encrypt security keys in user interface 3. Enhance RSTP compatibility	Bugs Fixed: 1. Cross-site scripting vulnerability 2. Denial of service attack vulnerability 3. Privilege escalation vulnerability 4. SSL v2/v3 vulnerability in https 5. Web console cannot be accessed due to SNMP get bulk 6. Enhance RSTP compatibility 7. Specific CLI command cause switch reboot with default settings 8. Add a new VLAN will change IGMP querier state from disable to enable 9. Saving configuration to ABC-01 cannot be performed via IE browser 10. Correct RSTP auto-edge behavior 11. Rate limit cannot be set in web UI 12. PTP timestamp error in announce message 13. Display issue with JAVA applet 14. Telnet hangs after SSH disabled 15. Correct authorization of Radius/TACACS+ login Changes: N/A	N/A



Software Relea

Software Name: PT-508 Series Firmware

Vers No		Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
3.5	N/A	N/A	PT-508 series	New Features: N/A Enhancements: 1. Add web interface for loop-protection enable/disable 2. Add web interface for SSH/SSL key generation 3. Add web interface and CLI for multi port mirroring 4. Add SNMP MIB for SFP DDM 5. Add web interface/CLI/SNMP for NTP/SNTP client settings enable/disable independently	Bugs Fixed: 1. Login fail in CLI mode when password is with special character 2. Hybrid VLAN lacks of SNMP MIB object 3. SFP DDM display inaccurate value 4. IEEE 1588 PTP cannot function correctly 5. The system restricts to import configuration if system name is too long 6. Login authentication failed if the radius server does not support privilege levels assignment 7. DIP switch coupler On/Off is malfunction Changes: N/A	N/A
3.1	N/A	N/A	PT-508 series	New Features: N/A Enhancements: 1. Pass ODVA EtherNet/IP certificate 2. Add some minor SNMP OIDs 3. Enhance multicast performance 4. Add version number in MIB file	Bugs Fixed: 1. NTP cannot synchronize time in default setting 2. NTP client function cannot work with Windows XP NTP server 3. Firmware Upgrade Failed when IEEE 802.1x is enabled 4. Switch reboots when receiving IGMP v3 packets (commonly used in Windows 7) Changes: N/A	N/A



Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
3.0	N/A	N/A	PT-508 series	authentication 9. Egress rate limit	Bugs Fixed: N/A Changes: N/A	N/A
2.6	N/A	N/A	PT-508 series	functions of Turbo Chain, IPv6, Modbus/TCP, IEEE 1588 PTP, SNMP Inform, LLDP, DHCP Option 82,	Bugs Fixed: N/A Changes: N/A	N/A