**MOXA**®  **Software Release Note**                                                      <span style="color:red">**Software Name: W321-LX Series Firmware**</span>

| Version No. | Build Code | Supported OS | Apply to (full model name) | New Feature(s) | Change(s) | Enhancement(s) | Bug(s) Fixed | Additional Note(s) |
|---|---|---|---|---|---|---|---|---|
| 3 | Build 13032818 | Linux | W321-LX | Digital Input/Output | 1. Upgrade Linux kernel to 2.6.38<br>2. Use 802.11 b/g/n WiFi | N/A | Bootloader bug fixed and upgrade version. | Office release |
| 3.1 | Build 14041111 | Linux | W321-LX | N/A | 1. Update WIFI channel for FCC requirement.<br>2. Update hfm model name from "W321" to "W321V2" | N/A | N/A | Office release |