Firmware for ioMirror E3200 Series (E3210) Release Notes

Version: v1.3	Build: Build16052610
Release Date: Jun 03, 2016	

Applicable Products

ioMirror E3210

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

• Fixed DI return value reverse (Modbus Address 0x0000 to 0x0007).
• Fixed peer-to-peer disconnection after about 3-month operation.

Changes

N/A

Notes

N/A

Version: v1.2	Build: Build07121011
Release Date: N/A	

Applicable Products

ioMirror E3210

Supported Operating Systems

N/A

New Features

• Added Locating I/O function in General Settings.
• Added Modbus address function code=0x08 for "ECHO" function.
• Counter overflow status is displayed on Channel Settings, and can be manually cleared.

Enhancements

• Modify the length of "module loc" and "desc".
• Modify the web console to add Alarm Mode function (blinking mode and do mode) on Web Mirror Settings page
• Modify the web console to add Hold Last Status function on Web Do Channel Settings page.

Bugs Fixed

• Fix the connection problem that occasionally switching between on-line and off-line between ioMirror.
• Fix the slow response problem while connecting to multiple ioMirror.
• Fix the problem that reset the ioMirror will block the system after firmware upgrade.
• Fix the problem that web console will not display all items.

Changes

N/A

Notes

• The firmware supports ioEventLog V1.1 only.
• OS version: MOS V3.2.15A (modification of queue priority).