



## Firmware for TN-4500A Series (TN-4524A, TN-4528A) Release Notes

<b>Version:</b> v3.9	<b>Build:</b> N/A
<b>Release Date:</b> Nov 16, 2021	

### Applicable Products

TN-4524A, TN-4528A

### Supported Operating Systems

N/A

### New Features

N/A

### Enhancements

N/A

### Bugs Fixed

- If a configuration conflict occurs during firmware upgrading, the device password is unexpectedly changed.
- Some locked fields on the VLAN page in the web UI are editable when loading the page for the first time.
- If an event log is produced during a firmware upgrade, the firmware upgrade process will fail.

### Changes

N/A

### Notes

N/A



<b>Version: v3.6</b>	<b>Build: 19011009</b>
<b>Release Date: Jun 06, 2019</b>	

### **Applicable Products**

TN-4524A, TN-4528A

### **Supported Operating Systems**

N/A

### **New Features**

- Includes Security Guideline level 2, DNS Server, ACL, and DHCP Filter functions.

### **Enhancements**

- Router Alert option on all IGMP packets.

### **Bugs Fixed**

- Y2K 2038 issue.
- Web UI does not accept valid device IP addresses with 255 values in the Set Device IP field..
- DHCP discovery issue for duplicate unicast in Option 82 relay mode.
- Cannot access device using HTTP/HTTPS after IP is changed.
- NTP query interval issue.

### **Changes**

- Changed the DHCP option-82 Relay and Set Device IP settings for all ports.

### **Notes**

N/A



<b>Version: v3.5</b>	<b>Build: 17072820</b>
<b>Release Date: Jan 17, 2019</b>	

**Applicable Products**

N/A

**Supported Operating Systems**

N/A

**New Features**

- Add Router Alert option

**Enhancements**

N/A

**Bugs Fixed**

- ABC-01 operation issue
- Static Port Lock issue
- Non-querier port forward Multicast stream

**Changes**

N/A

**Notes**

N/A