



## Firmware for PT-G503 Series Release Notes

<b>Version: v5.1</b>	<b>Build: N/A</b>
<b>Release Date: Apr 13, 2022</b>	

### Applicable Products

N/A

### Supported Operating Systems

N/A

### New Features

N/A

### Enhancements

N/A

### Bugs Fixed

- The PTP boundary clock Best Master Clock algorithm behaves abnormally.
- The P2P path delay correction field does not update correctly.
- The SNMP polling function for MXview always fails.
- Forcing the port speed to 100M/10M in the Web UI does not work.

### Changes

N/A

### Notes

N/A



<b>Version: v5.0</b>	<b>Build: Build_18071716</b>
<b>Release Date: Dec 09, 2019</b>	

### **Applicable Products**

PT-G503 Series

### **Supported Operating Systems**

N/A

### **New Features**

- The flash memory had been replaced.

### **Enhancements**

N/A

### **Bugs Fixed**

- The PT-G503 Series could not upload firmware using the ABC-02 Series.

### **Changes**

N/A

### **Notes**

Product versions V1.0.2 and prior are compatible with all firmware versions. Product versions V2.0.0 and later are compatible with firmware V5.0 and later.



<b>Version: v4.3</b>	<b>Build: Build_17090110</b>
<b>Release Date: Oct 18, 2017</b>	

### **Applicable Products**

PT-G503-PHR-PTP-HV, PT-G503-PHR-PTP-WV

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

- PTP: Supports BC/TC P2P/E2E.
- PTP: Supports Power profile.
- PTP: Supports 2-step to 1-step.
- IEC 62439-3: Configurable supervision frame.
- Security: Added a warning message for when the default password has not changed yet.
- Security: Encrypts security keys in the user interface.

### **Bugs Fixed**

- Cross-site scripting vulnerability.
- Denial of Service attack vulnerability.
- Privilege escalation vulnerability.
- SSL v2/v3 vulnerability in HTTPS.
- Web console cannot be accessed when the SNMP get bulk service is running.
- Specific CLI command caused the switch to reboot with default settings.
- PTP timestamp error in announce Message.
- System rebooted after specific CLI commands.
- Telnet hangs when SSH is disabled.
- For PT-G503 models that use SFP-1G Series cannot link up with EDR-G903 models.

### **Changes**

- Renamed RSTP transparent to RSTP Grouping.

### **Notes**

N/A



<b>Version: v4.2</b>	<b>Build: Build_17022316</b>
<b>Release Date: N/A</b>	

**Applicable Products**

PT-G503-PHR-PTP-HV, PT-G503-PHR-PTP-WV

**Supported Operating Systems**

N/A

**New Features**

N/A

**Enhancements**

N/A

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A



<b>Version: v4.1</b>	<b>Build: N/A</b>
<b>Release Date: N/A</b>	

**Applicable Products**

PT-G503-PHR-PTP-HV, PT-G503-PHR-PTP-WV

**Supported Operating Systems**

N/A

**New Features**

- First release for PT-G503 Series.

**Enhancements**

N/A

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A