

Software Name: EDS-508A Series Firmware

Version No.	Build Date No./Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
3.8	Build_17041115	N/A	EDS-508A	New Features: N/A Enhancements: 1. Add warning message when default password was not changed 2. Encrypt security Keys in user interface 3. Enhance RSTP compatibility	Bugs Fixed: 1. Cross-site scripting vulnerability. 2. Denial of Service attack vulnerability. 3. Privilege escalation vulnerability. 4. SSL v2/v3 vulnerability in https. 5. Web console cannot be accessed due to SNMP get bulk. 6. Specific CLI command cause switch reboot with default settings. 7. Add a new VLAN will change IGMP querier state from disable to enable. 8. Saving configuration to ABC-01 cannot be performed via IE browser. 9. Rate limit cannot be set in web UI. 10. Telnet hangs after SSH disabled. 11. Correct RSTP edge definition in exported configuration file. 12. Correct authorization of Radius/TACACS+ login. 13. Correct RSTP Auto-Edge behavior. 14. After upgrade firmware, the system maybe warm start when the user login the switch. Changes: N/A	N/A
3.4	Build_14121010	N/A	EDS-508A	New Features: N/A Enhancements: N/A	Bugs Fixed: 1. Web user interface display errors under Java 8 environment. Changes: N/A	N/A

Software Name: EDS-508A Series Firmware

Version No.	Build Date No./Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
3.3	N/A	N/A	EDS-508A	<p>New Features: N/A</p> <p>Enhancements: 1. Add web interface for loop-protection enable/disable 2. Add web interface for SSH/SSL key generation 3. Add web interface/CLI/SNMP for NTP/SNTP client settings</p>	<p>Bugs Fixed: 1. Login fail in CLI mode when password contained special character 2. Hybrid VLAN lacks of SNMP MIB object 3. IEEE 1588 PTP cannot function correctly 4. Restricts configuration import if the system name is too long 5. Login authentication failed if the radius server does not support privilege levels assignment 6. DIP switch "Coupler" On/Off is malfunction</p> <p>Changes: N/A</p>	N/A
3.1	N/A	N/A	EDS-508A	<p>New Features: N/A</p> <p>Enhancements: 1. Pass ODVA EtherNet/IP certificate 2. Add some minor SNMP OIDs 3. Enhance multicast performance 4. Add version number in MIB file</p>	<p>Bugs Fixed: 1. NTP cannot synchronize time in default setting 2. NTP client function cannot work with Windows XP NTP server 3. Firmware Upgrade Failed when IEEE 802.1x is enabled 4. Switch reboots when receiving IGMP v3 packets (commonly used in Windows 7)</p> <p>Changes: N/A</p>	N/A

Software Name: EDS-508A Series Firmware

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
3	N/A	N/A	EDS-508A	New Features: 1. RSTP-2004 2. MSTP 3. NTP Server/Client 4. IEEE 1588 PTP V2 5. RADIUS and TACACS+ for user login authentication 6. RADIUS for 802.1x port authentication 7. Hybrid VLAN 8. Command Line Interface 9. EtherNet/IP 10. Egress rate limit 11. Unknown unicast filtering 12. CPU loading monitoring 13. Change IP without reboot 14. DHCP Discover retry configuration 15. GARP timer adjustment 16. Loop-protection 17. Link Fault Shutdown (Disable mode in "Rate Limit" function) Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A
2.6	N/A	N/A	EDS-508A	New Features: N/A Enhancements: 1. Enhance Turbo Chain function	Bugs Fixed: N/A Changes: N/A	N/A

Software Name: EDS-508A Series Firmware

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
2.5	N/A	N/A	EDS-508A	<p>New Features: 1. Support TurboPack™ 2009 (add new managed functions of Turbo Chain, IPv6, Modbus/TCP, IEEE 1588 PTP, SNMP Inform, LLDP, DHCP Option 82, Firefox, and SSH)</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed: N/A</p> <p>Changes: N/A</p>	N/A
2.1	N/A	N/A	EDS-508A	<p>New Features: 1. Add new Turbo Ring (“Turbo Ring V2”) Function 2. Add new Ring Coupling Function 3. Add Daylight Saving Function</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed: N/A</p> <p>Changes: N/A</p>	N/A
1.3	N/A	N/A	EDS-508A	<p>New Features: 1. Add Syslog Function 2. Add Restart Function</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed: N/A</p> <p>Changes: N/A</p>	N/A
1.2	N/A	N/A	EDS-508A	<p>New Features: 1. New firmware release for EDS-508A series.</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed: N/A</p> <p>Changes: N/A</p>	N/A