

Software Name: PT-7528 series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
4.0	Build_17113010	N/A	PT-7528 series	<p>New Features:</p> <ol style="list-style-type: none"> Add configuration file encryption setting <p>Enhancements:</p> <ol style="list-style-type: none"> Writable MMS attributes of switch description: <ol style="list-style-type: none"> LPHD1\$DC\$PhyNam\$model LPHD1\$DC\$PhyNam\$location 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> Stack-based buffer overflow vulnerability Risky cryptographic algorithm vulnerability Hard-coded cryptographic key vulnerability Hard-coded password vulnerability RSTP 40 nodes failed issue Switch name description change cause configuration import to fail issue Turbo Ring v1 failed issue on firmware v3.8 Remove misplaced UI config: IEEE 1588v2 E2E 1-step TC 	Firmware version v4.0 and later are compatible with all hardware reversion of PT-7528.
3.8	Build_17041116	N/A	PT-7528 series	<p>Enhancements:</p> <ol style="list-style-type: none"> Add warning message when default password was not changed Encrypt security keys in user interface Enhance RSTP compatibility 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> Cross-site scripting vulnerability Denial of service attack vulnerability Privilege escalation vulnerability SSL v2/v3 vulnerability in https Web console cannot be accessed due to SNMP get bulk Specific CLI command cause switch reboot with default settings Add a new VLAN will change IGMP querier state from disable to enable Correct RSTP auto-edge behavior Rate limit cannot be set in web UI PTP timestamp error in announce message Remove 1588v2 PTP message of IEC 61850 QoS Telnet hangs after SSH disabled Correct RSTP edge definition in exported configuration file Correct authorization of Radius/TACACS+ login" 	Firmware version v3.8 and before are only compatible with hardware reversion PT-7528-TX V2.0.1 and before; PT-7528-FX V1.0.1 and before.
3.6	Build_15060211	N/A	PT-7528 series	<p>Enhancements:</p> <ol style="list-style-type: none"> Support MxView. MMS data modeling support Fiber Check info. Add 100FX Ports Disable Function. 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> Fixed Java 7 Java Applet Certification Problem Fix SFP plug-in fail issue 	Firmware version v3.6 and before are only compatible with hardware reversion PT-7528-TX V2.0.1 and before; PT-7528-FX V1.0.1 and before.

Software Name: PT-7528 series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
3.5	N/A	N/A	PT-7528 series	Enhancements: 1.Add MSC/SSC module information. 2.Modify link change detection mechanism. 3.Modify Turbo Chain sending TCN packet frequency.	N/A	Firmware version v3.5 and before are only compatible with hardware reversion PT-7528-TX V2.0.1 and before; PT-7528-FX V1.0.1 and before.
3.0	N/A	N/A	PT-7528 series	N/A	N/A	Firmware version v3.0 and before are only compatible with hardware reversion PT-7528-TX V2.0.1 and before; PT-7528-FX V1.0.1 and before.