



Firmware for NPort 5400 Series (Rev. 3.x) Release Notes

Version: v3.12	Build: Build 17030709
Release Date: Mar 15, 2017	

Applicable Products

NPort 5410, NPort 5430I, NPort 5430, NPort 5450, NPort 5450-T, NPort 5450I, NPort 5450I-T

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- The user's password and SNMP community name may be exposed by a buffer overflow issue.

Changes

N/A

Notes

N/A



Version: v3.11	Build: Build 16100411
Release Date: N/A	

Applicable Products

NPort 5410, NPort 5430, NPort 5430I, NPort 5450, NPort 5450-T, NPort 5450I, NPort 5450I-T

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- Enhanced web login security and supports 5 users logged in simultaneously.
- Extended HTTP challenge ID length from 32 bits to 256 bits.
- IP of NPort can be set to addresses ending with 0 or 255.
- Enabled the default password "moxa".
- Increased CSRF protection mechanism.
- Increased XSS protection mechanism.
- Supports "ARP probe" in RFC5227. NPort would respond to ARP requests with sender IP address 0.0.0.0.

Bugs Fixed

- NPort cannot send e-mail using Google's SMTP server.
- In pair connection mode, master does not pull down RTS/DTR signal after the TCP connection is broken.
- Command port sends lots of "D_ASPP_CMD_ALIVE" packets after running for 50 days.
- NPort may reboot or hang from several buffer overflow attacks through Telnet, SSH, DSCI, SNMP, HTTP, and HTTPS.

Changes

N/A

Notes

N/A



Version: v3.10	Build: Build 15041515
Release Date: N/A	

Applicable Products

NPort 5410, NPort 5430, NPort 5430I, NPort 5450, NPort 5450-T, NPort 5450I, NPort 5450I-T

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- Uses model name instead of "NULL" for SNMP object "sysDescr".
- Supports connecting to the server by domain name and the server IP will change dynamically.
- Supports updating the ARP table by gratuitous ARP.
- Supports time synchronization with an NTPv4 server.

Bugs Fixed

- If an SNMP GETNEXT command is issued on an object that does not exist, 'no such name error' is displayed.
- When DHCP renews IPs, if the IP was originally given by a relay agent, NPort should send a DHCP request to the relay agent, not the DHCP server.
- In Real COM mode, when the modem status of the NPort's serial port is changed frequently, the NPort will sometimes fail to notify the change to the driver.
- In reverse telnet mode, the NPort will try to subnegotiate the COM port control options without option negotiation first.

Changes

N/A

Notes

N/A