

# Windows Driver Manager (for Windows 7, Server 2008, or later) Release Notes

Version: v3.1

Build: 19052118

## Release Date: Aug 01, 2019

#### **Applicable Products**

NPort S9450I Series, NPort S9650I Series, NPort W2150A/W2250A Series, OnCell G3100-HSPA Series, OnCell G3101/G3201 Series, OnCell G3150A-LTE Series, OnCell G3470A-LTE Series, WE-2100T, CN2510 Series, CN2600 Series, NPort 5200 Series, NPort 5400 Series, NPort 5600 Series, NPort 5600-DT Series, NPort 6400/6600 Series, NPort 5100A Series, NPort P5150A Series, NPort 5200A Series, NPort 5600-DTL Series, NPort 6150/6260 Series, NPort Express Series, NPort IA5000 Series, NPort IA5000A Series, NPort IA5000A-I/O Series, NPort IAW5000A-I/O Series, MiiNePort E1 Series, MiiNePort E2 Series, MiiNePort E3 Series, NPort S000 Series

## **Supported Operating Systems**

Windows 10, Windows 7, Windows 8, Windows 8.1, Windows Server 2008 R2, Windows Server 2012 R2, Windows Server 2016, Windows Server 2019

## **New Features**

• Supports Windows Server 2019.

• Supports VMware ESXi v6.7.0 for the following OSes: Windows 7 x86, Windows 8 x86, Windows 8.1 x64, Windows Server 2016, Windows 10 x64, Windows Server 2019

## **Enhancements**

N/A

## **Bugs Fixed**

N/A

#### Changes

N/A

## Notes

N/A



Version: v3.0

**Build: N/A** 

Release Date: Aug 23, 2018

# Applicable Products

N/A

## **Supported Operating Systems**

Windows 10, Windows 7, Windows 8, Windows 8.1, Windows Server 2008 R2, Windows Server 2012, Windows Server 2012 R2, Windows Server 2016

## **New Features**

N/A

## Enhancements

Upgraded OpenSSL Library.

## **Bugs Fixed**

- Fixed the network timeout issue in NPort Windows Driver Manager.
- When using the NPort 6000 in high security mode in Windows 10, may not be able to open ports.
- TCP port 60950 and 60966 are occupied even when not in use.
- Fixed BSOD which occurs when driver cancels pending IRPs.

## Changes

Divided driver into separate versions, v3.0 supports Windows 7/8/8.1/10 and Windows Server 2008 R2/2012/2012R2.

## Notes

This version is divided into two separate drivers (v2.0 and v3.0) to support different Windows platforms.