



Firmware for NPort 5000AI-M12 Series (5450AI-M12) Release Notes

Version: 1.3	Build: Build 17030709
Release Date: Mar 15, 2017	

Applicable Products

NPort 5450AI-M12

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- The user's password and SNMP community name may be exposed by a buffer overflow issue.

Changes

N/A

Notes

N/A



Version: v1.2	Build: Build 16100410
Release Date: N/A	

Applicable Products

NPort 5450AI-M12

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- Enhanced web login security and supports 5 users logged in simultaneously.
- Extended HTTP challenge ID length from 32 bits to 256 bits.
- IP of NPort can be set to addresses ending with 0 or 255.
- Enabled the default password "moxa".
- Increased CSRF protection mechanism.
- Increased XSS protection mechanism.
- Supports "ARP probe" in RFC5227. NPort would respond to ARP requests with sender IP address 0.0.0.0.

Bugs Fixed

- NPort cannot send e-mail using Google's SMTP server.
- In pair connection mode, master does not pull down RTS/DTR signal after the TCP connection is broken.
- Command port sends lots of "D_ASPP_CMD_ALIVE" packets after running for 50 days.
- NPort may reboot or hang from several buffer overflow attacks through Telnet, SSH, DSCI, SNMP, HTTP, and HTTPS.
- Too many connections to the HTTP server at the same time would block new connections for a while.

Changes

N/A

Notes

N/A



Version: v1.1	Build: Build 15041515
Release Date: N/A	

Applicable Products

NPort 5450AI-M12

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- Uses model name instead of "NULL" for SNMP object "sysDescr".
- Supports connecting to the server by domain name and the server IP will change dynamically.
- Supports updating the ARP table by gratuitous ARP.
- Supports time synchronization with an NTPv4 server.
- Supports RFC2217 NOTIFY-LINESTATE for Transfer Shift Register Empty and Transfer Holding Register Empty.

Bugs Fixed

- If an SNMP GETNEXT command is issued on an object that does not exist, 'no such name error' is displayed.
- In reverse telnet mode, the NPort will try to subnegotiate the COM port control options without option negotiation first.
- In RFC2217 Mode, if the Ethernet data has many FF characters, some data may be lost while passing the data to the serial side.
- Unable to see the baud rate through a Telnet console on the "View settings" side.
- Web Console cannot display web pages when refreshing or switching web pages frequently using IE8.

Changes

N/A

Notes

N/A



Version: v1.0	Build: Build 12072410
Release Date: N/A	

Applicable Products

NPort 5450AI-M12

Supported Operating Systems

N/A

New Features

- First release.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A