

Software Name: Firmware for NPort 6100/6200 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
1.17	N/A	null	N/A	<p>New Features:</p> <ol style="list-style-type: none"> 1. Supports new Micron flash due to component end-of-life. 2. Supports 12-byte serial numbers. 3. Supports the RTC RX8130CE chip. <p>Enhancements:</p> <ol style="list-style-type: none"> 1. Disabled TCP port 14900. 2. Upgraded Dropbear SSH to 2017.75. 3. Updated openssl library to 1.0.2k. 4. Serial and Web console can use an empty pre-shared key to export plaintext config files. 5. Radius and Tacacs+ can use attributes to manage user group policy. 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. NPort may reboot when opening port twice in Reverse RealCOM mode with secure enabled. 2. Failing to modify serial settings through a telnet/ssh console. 3. Failing to set the prefix netmask of the accessible IP list. <p>Changes:</p> <p>N/A</p>	N/A