

MSB Linux kernel 5.x.x driver Release Notes

Version: v5.1 Build: 21102516

Release Date: Oct 25, 2021

Applicable Products

CP-168EL-A, POS-104UL Series, CP-134U Series, CP-114UL Series, CP-104UL/104JU Series, CP-104N Series, CP-102E/102EL Series, CP-118U/138U Series, CP-116E-A, CP-602E-I Series, CP-134EL-A-I Series, CP-132N Series, CP-168U Series, CP-102U/102UL Series, CP-118EL-A, CP-132UL Series, CP-102N Series, CP-118E-A-I/138E-A-I Series, CP-114EL Series, CP-134N Series, CP-602U-I Series, CP-114N Series, CP-132EL Series, CP-112UL Series, CP-104EL-A Series

Supported Operating Systems

Linux Kernel 5.x

New Features

• Supports Arm64 platform.

Enhancements

N/A

Bugs Fixed

- The muestty command could not set device's serial interface type to RS-232.
- Baud rate mismatch when Linux kernel version is newer than 5.4.
- Utility compilation failed for Debian and Kylin.

Changes

- Downgraded software license from GPLv3 to GPLv2.
- Avoids using mxinstall when compiling utilities that are not supported in the Arm platform.

Notes

N/A



Version: v5.0 Build: 19090215

Release Date: Dec 31, 2019

Applicable Products

CP-134EL-A-I Series, CP-116E-A, CP-102E/102EL Series, CP-104EL-A Series, CP-168EL-A, CP-132EL Series, CP-114EL Series, CP-118EL-A, CP-102U/102UL Series, CP-104UL/104JU Series, CP-168U Series, POS-104UL Series, CP-132UL Series, CP-134U Series, CP-112UL Series, CP-114UL Series, CP-118U/138U Series

Supported Operating Systems

Linux Kernel 5.x

New Features

• First release.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A