

Software Name: ioSearch utility

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
1.5	Build11090818	Win2000 WinXP (x86)	ioLogik E1210, ioLogik E1211, ioLogik E1212, ioLogik E1213, ioLogik E1214, ioLogik E1240, ioLogik E1241, ioLogik E1242, ioLogik E1260, ioLogik E1262, ioLogik R1241	New Features: N/A Enhancements: 1. Support modifying IP, Gateway, Subnet Mask or Server name for a batch of same models. 2. Support simultaneously upgrading different models' firmware. 3. Support searching devices by keyword of the server name. 4. Support import/export device	Bugs Fixed: N/A Changes: N/A	N/A
1.6	Build11112811	Win2000 WinXP (x86)	ioLogik E1210, ioLogik E1211, ioLogik E1212, ioLogik E1213, ioLogik E1214, ioLogik E1240, ioLogik E1241, ioLogik E1242, ioLogik E1260, ioLogik E1262, ioLogik R1241	New Features: N/A Enhancements: N/A	Bugs Fixed: 1. The Netmask cannot be 255.0.0.0. Changes: N/A	N/A
1.8	Build12080118	Win2000 WinXP (x86)	ioLogik E1210, ioLogik E1211, ioLogik E1212, ioLogik E1213, ioLogik E1214, ioLogik E1240, ioLogik E1241, ioLogik E1242, ioLogik E1260, ioLogik E1262, ioLogik R1241, ioLogik E1510-T, ioLogik E1512-T	New Features: 1. ioLogik E1510-M12-T, ioLogik E1512-M12-T are supported Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A
1.10	Build13032918	Win2000 WinXP (x86)	ioLogik E1210, ioLogik E1211, ioLogik E1212, ioLogik E1213, ioLogik E1214, ioLogik E1240, ioLogik E1241, ioLogik E1242, ioLogik E1260, ioLogik E1262, ioLogik R1210, ioLogik R1212, ioLogik R1214, ioLogik R1240, ioLogik R1241, ioLogik E1510-T, ioLogik E1512-T	New Features: 1. ioLogik R1210(-T), ioLogik R1212(-T), ioLogik R1214(-T), ioLogik R1240(-T), ioLogik R1241(-T) are supported Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A
1.12	Build14041118	Win2000 WinXP (x86)	ioLogik E1210, ioLogik E1211, ioLogik E1212, ioLogik E1213, ioLogik E1214, ioLogik E1240, ioLogik E1241, ioLogik E1242, ioLogik E1260, ioLogik E1262, ioLogik R1210, ioLogik R1212, ioLogik R1214, ioLogik R1240, ioLogik R1241, ioLogik E1510-T, ioLogik E1512-T	New Features: N/A Enhancements: 1. Support MOXA green core design	Bugs Fixed: N/A Changes: N/A	N/A

Software Name: ioSearch utility

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
1.14	Build16012114	Microsoft Windows 7/8/10, Microsoft Windows Server 2003/2008/2012	ioLogik E1210, ioLogik E1211, ioLogik E1212, ioLogik E1213, ioLogik E1214, ioLogik E1240, ioLogik E1241, ioLogik E1242, ioLogik E1260, ioLogik E1262, ioLogik R1210, ioLogik R1212, ioLogik R1214, ioLogik R1240, ioLogik R1241, ioLogik E1261W-T, ioLogik E1261- WP-T, ioLogik E1261H-T, ioLogik E1263H-T, ioLogik E1510-T, ioLogik E1512-T	New Features: 1. ioLogik E1261W-T, ioLogik E1261-WP-T, ioLogik E1261H-T, ioLogik E1263H-T are supported Enhancements: 1. Added 4-20 mA mode (raw data: 0-65535) for ioLogik R1240 analog input channel	Bugs Fixed: 1. Fixed ioLogik R1241 AO raw data from 0-65535 to 0-4095 Changes: N/A	1. Use ioSearch V1.12 to update ioLogik R1241 firmware from V1.0/V1.1 to V1.2. 2. DO NOT use ioSearch V1.14 or later to configure ioLogik R1241 with V1.0/V1.1 firmware.
1.15	Build16091417	Microsoft Windows 7/8/10, Microsoft Windows Server 2003/2008/2012	ioLogik E1210, ioLogik E1211, ioLogik E1212, ioLogik E1213, ioLogik E1214, ioLogik E1240, ioLogik E1241, ioLogik E1242, ioLogik E1260, ioLogik E1262, ioLogik R1210, ioLogik R1212, ioLogik R1214, ioLogik R1240, ioLogik R1241, ioLogik E1261W-T, ioLogik E1261- WP-T, ioLogik E1261H-T, ioLogik E1263H-T, ioLogik E1510-T, ioLogik E1512-T	New Features: 1. Support EtherNet/IP activation function for the ioLogik E1200 series. 2. Added Help file. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A
2.0	Build17111410	Microsoft Windows 7/8/10, Microsoft Windows Server 2003/2008/2012	ioLogik E1210, ioLogik E1211, ioLogik E1212, ioLogik E1213, ioLogik E1214, ioLogik E1240, ioLogik E1241, ioLogik E1242, ioLogik E1260, ioLogik E1262, ioLogik R1210, ioLogik R1212, ioLogik R1214, ioLogik R1240, ioLogik R1241, ioLogik E1261W-T, ioLogik E1261- WP-T, ioLogik E1261H-T, ioLogik E1263H-T, ioLogik E1510-T, ioLogik E1512-T	New Features: 1. Changed EtherNet/IP per unit licensing policy to one unit/license file only policy Enhancements: 1. Revised help file including RESTful API and EtherNet/IP	Bugs Fixed: N/A Changes: N/A	When updating firmware version V3.0 or higher, use ioSearch V2.0 or higher version to upgrade.