



Firmware for VPort P16-1MP-M12-IR Series Release Notes

Version: v1.4	Build: Build_18030811
Release Date: Mar 08, 2018	

Applicable Products

VPort P16-1MP-M12-IR-CAM36, VPort P16-1MP-M12-IR-CAM80, VPort P16-1MP-M12-IR-CAM36-T, VPort P16-1MP-M12-IR-CAM80-T, VPort P16-1MP-M12-IR-CAM36-CT, VPort P16-1MP-M12-IR-CAM80-CT, VPort P16-1MP-M12-IR-CAM36-CT-T, VPort P16-1MP-M12-IR-CAM80-CT-T

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- Upgraded the BIOS to v1.3.
- Changed the serial no. to 12 digits in the web console.

Bugs Fixed

N/A

Changes

N/A

Notes

N/A



Version: v1.3	Build: Build_17031716
Release Date: N/A	

Applicable Products

VPort P16-1MP-M12-IR-CAM36, VPort P16-1MP-M12-IR-CAM80, VPort P16-1MP-M12-IR-CAM36-T, VPort P16-1MP-M12-IR-CAM80-T, VPort P16-1MP-M12-IR-CAM36-CT, VPort P16-1MP-M12-IR-CAM80-CT, VPort P16-1MP-M12-IR-CAM36-CT-T, VPort P16-1MP-M12-IR-CAM80-CT-T

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- Enhanced the tamper alarm function.

Bugs Fixed

- MXNVR-RO Discovery causing ONVIF process crash.
- VMD & Tamper events not working on Genetec VMS.
- Web server crash by Nessus Vulnerability Scanner.

Changes

- Removed Timing info present from VUI.
- Image sensor de-noise function on/off option.
- Updated AWB algorithm.

Notes

N/A



Version: v1.2	Build: Build_16031718
Release Date: N/A	

Applicable Products

VPort P16-1MP-M12-IR-CAM36, VPort P16-1MP-M12-IR-CAM80, VPort P16-1MP-M12-IR-CAM36-T, VPort P16-1MP-M12-IR-CAM80-T, VPort P16-1MP-M12-IR-CAM36-CT, VPort P16-1MP-M12-IR-CAM80-CT, VPort P16-1MP-M12-IR-CAM36-CT-T, VPort P16-1MP-M12-IR-CAM80-CT-T

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- Streaming server may not respond when taking a snapshot.
- Camera webserver crashing when triggering CGI for a long time.
- SOAP connection occasionally returning an HTTP 500 internal server error.

Changes

- Improved VMS interoperability.

Notes

N/A