

Software Name: VPort P16-1MP-M12-IR firmware

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
1.4	Build_18030811	N/A	VPort P16-1MP-M12-IR-CAM36 VPort P16-1MP-M12-IR-CAM80 VPort P16-1MP-M12-IR-CAM36-T VPort P16-1MP-M12-IR-CAM80-T VPort P16-1MP-M12-IR-CAM36-CT VPort P16-1MP-M12-IR-CAM80-CT VPort P16-1MP-M12-IR-CAM36-CT-T VPort P16-1MP-M12-IR-CAM80-CT-T	New Features: N/A  Enhancements: 1. Upgrade the BIOS to V1.3 2. Change the serial no. to 12 digits on web console	Bugs Fixed: N/A  Changes: N/A	N/A
1.3	17031716	N/A	VPort P16-1MP-M12-IR-CAM36 VPort P16-1MP-M12-IR-CAM80 VPort P16-1MP-M12-IR-CAM36-T VPort P16-1MP-M12-IR-CAM80-T VPort P16-1MP-M12-IR-CAM36-CT VPort P16-1MP-M12-IR-CAM80-CT VPort P16-1MP-M12-IR-CAM36-CT-T VPort P16-1MP-M12-IR-CAM80-CT-T	New Features: N/A  Enhancements: N/A	Bugs Fixed: Fix MXNVR-RO Discovery cause onvif process crash Fix VMD & Tamper event not working on Genetec VMS Fix web server crash by Nessus Vulnerability Scanner  Changes: New Tamper function Remove Timing info present from VUI Image sensor de-noise function on/off option Update AWB algorithm	N/A
1.2	16031718	N/A	VPort P16-1MP-M12-IR-CAM36 VPort P16-1MP-M12-IR-CAM80 VPort P16-1MP-M12-IR-CAM36-T VPort P16-1MP-M12-IR-CAM80-T VPort P16-1MP-M12-IR-CAM36-CT VPort P16-1MP-M12-IR-CAM80-CT VPort P16-1MP-M12-IR-CAM36-CT-T VPort P16-1MP-M12-IR-CAM80-CT-T	New Features: N/A  Enhancements: N/A	Bugs Fixed: Fixed sometimes streaming server may not response when doing snapshot Fixed the issue of DUT webserver crash when triggering CGI for long time Fixed sometimes SOAP connection return HTTP 500 internal server error  Changes: 1. Improve VMS interoperability	N/A