



Software Release Note

Software Name: VPort 56-2MP series

Version No.	Build Code	Supported OS	Apply to (full model name)	New Feature(s)	Change(s)	Enhancement(s)	Bug(s) Fixed	Additional Note(s)
V1.2	Build 14062014	N/A	VPort 56-2MP-CAM10X VPort 56-2MP-CAM10X-T VPort 56-2MP-CAM10X-S-SC VPort 56-2MP-CAM10X-S-SC-T	1. Support the standard/wide temperature model. 2. Support fiber model.	Support MJPEG 1080P	1. Support RTCP for RTSP stream. 2. Allow characters as '@' ':' '_' '-' for SMTP user account. 3. Support IE10 above. 4. Show video stream on non-IE browsers. 5. The default setting of event alarm is enable. 6. Show a warning message in upgrade process. 7. Support 128 PTZ preset point including zoom position 8. Support HTTPS for upgrading firmware and importing/exporting configuration file	1. Preview issue in some conditions in DynaStream 2. Transparent PTZ will lost characters 3. Can't configure odd port number on SNMP multicast video port 4. Fail in transmitting snapshot images to FTP server when the FTP server is in link down 5. Abnormal webpage display in IE11 (Same connection type in Chrome & Firefox) 6. Fail in AGC function	1.SVN :11073 2.Non-ONVIF version 3.MOXA-VPORT56-2MP-MIB-V1.2-dev.my
v2.0	Build 14111311	N/A	VPort 56-2MP-CAM10X VPort 56-2MP-CAM10X-T VPort 56-2MP-CAM10X-S-SC VPort 56-2MP-CAM10X-S-SC-T	1.Support Onvif Profile S	Support Onvif Profile S			1.SVN :12252 2. ONVIF Profile S version 3.MOXA-VPORT56-2MP-MIB-V2.0-dev.my
v2.2	Build 16012120	N/A	VPort 56-2MP-CAM10X VPort 56-2MP-CAM10X-T VPort 56-2MP-CAM10X-S-SC VPort 56-2MP-CAM10X-S-SC-T	1. Support the dual firmware image mechanism. 2. Support the configuration / log file backup mechanism.	N/A	N/A	1.The bitflip in the OOB may crash the file system 2.Push hardware default button to run the hard default process.	