



## Firmware for UC-7120 Series (UC-7122-CE) Release Notes

<b>Version:</b> v2.4	<b>Build:</b> N/A
<b>Release Date:</b> Jan 20, 2020	

### Applicable Products

UC-7122-CE

### Supported Operating Systems

Windows CE 5.0

### New Features

N/A

### Enhancements

N/A

### Bugs Fixed

- Fixed system real time clock issue.
- Fixed Autorun function in norflash\startup which execute 2 times when insert USB disk.

### Changes

- Set default High water / Low water FIFO config to (8 / 0) for UART driver.

### Notes

N/A



<b>Version: v2.3</b>	<b>Build: 2018091011</b>
<b>Release Date: Apr 20, 2018</b>	

**Applicable Products**

UC-7124-CE, UC-7122-CE

**Supported Operating Systems**

Windows CE 5.0

**New Features**

- Function: A standalone flash block reserved for users based on firmware v2.3.

**Enhancements**

N/A

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A



<b>Version: v2.1</b>	<b>Build: 2012103017</b>
<b>Release Date: N/A</b>	

### **Applicable Products**

UC-7124-CE

### **Supported Operating Systems**

Windows CE 5.0

### **New Features**

- Function: A standalone flash block reserved for users based on firmware v2.2.
- UART driver specification: Supports different RX and TX parities.

### **Enhancements**

N/A

### **Bugs Fixed**

N/A

### **Changes**

N/A

### **Notes**

N/A