

Software Name: EDS-405A-PN Series Firmware

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
3.8	Build_17051216	N/A	EDS-405A-PN Series	<p>New Features: N/A</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed: 1. User account login authentication error in menu console mode.</p> <p>Changes: N/A</p>	N/A
3.7	Build_17031513	N/A	EDS-405A-PN Series	<p>New Features: N/A</p> <p>Enhancements: 1. Add warning message when default password was not changed 2. Encrypt security Keys in user interface</p>	<p>Bugs Fixed: 1. Cross-site scripting vulnerability 2. Denial of Service attack vulnerability 3. Privilege escalation vulnerability 4. SSL v2/v3 vulnerability in https 5. Web console cannot be accessed due to SNMP get bulk 6. Specific CLI command cause switch reboot with default settings 7. Add a new VLAN will change IGMP querier state from disable to enable. 8. Saving configuration to ABC-01 cannot be performed via IE browser 9. Rate limit cannot be set in web UI 10. Telnet hangs after SSH disabled 11. Correct RSTP edge definition in exported configuration file 12. Correct authorization of Radius/TACACS+ login 13. Correct RSTP Auto-Edge behavior 14. System could reboot after a period of operation while PROFINET is enabled</p> <p>Changes: N/A</p>	None

Software Name: EDS-405A-PN Series Firmware

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
3.2	Build_14121009	N/A	EDS-405A-PN Series	New Features: N/A Enhancements: N/A	Bugs Fixed: 1. Web user interface display errors under Java 8 environments. Changes: N/A	N/A
3.1	N/A	N/A	EDS-405A-PN Series	New Features: 1. Newly released for EDS-405A-PN series Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A