

Software Name: IKS-G6524A Firmware

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
	Build_17081010	INI/A	ICS-G7528A ICS-G7526A IKS- G6524A	8.Support MAC Authentication Bypass via RADIUS Authentication. 9.MAC Address Access Control List or MAC Address Filtering. 10. Protect Against MAC Flooding Attack by MAC Address Sticky. 11. NTP Authentication to Prevent NTP DDoS Attack. 12. Login Authentication: Support Primary & Backup Database Servers (RADIUS / TACACS+ / Local Account). 13. Login Authentication via RADIUS Server: Support	Bugs Fixed:  1. The device receive large amount of BPDU packet on the port not enabling the RSTP function might cause the device reboot.  2. '&' character in column of Switch name, Switch location, switch description in system info will not show on the how page information  Changes:  1. Rate limit add more option on ingress rate	N/A
4.2	Build_16112110	INI/A	ICS-G7528A ICS-G7526A IKS- G6524A	N/A Enhancements:	Bugs Fixed: N/A Changes: N/A	N/A



Software Name: IKS-G6524A Firmware

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
4.1	Build_15062312	ΙΝΙ/Δ	ICS-G7528A ICS-G7526A IKS- G6524A	groups)  2. Improve Turbo Chain link status check mechanism at	Device will reboot when using CLI command to backup device configuration to TFTP server.     Device will reboot when using CLI command to change SNMP v3 data encryption key and the length of key is over than 100 characters.  Changes: N/A	N/A
4	Build_14082811	IN/A	ICS-G7528A ICS-G7526A IKS- G6524A	1. First release.	Bugs Fixed: N/A Changes: N/A	N/A

Form number: PD.450 Version: 1.0 Page 2 of 2