



Windows Driver Manager (for Windows 7, Server 2008, or later) Release Notes

Version: v3.1	Build: 19080114
Release Date: Aug 01, 2019	

Applicable Products

NE 4100 Series, NPort 5000AI-M12 Series, NPort 5100A Series, NPort P5150A Series, NPort 5200A Series, NPort 5600-DTL Series, NPort 6150/6260 Series, NPort Express Series, NPort IA5000 Series, NPort IA5000A Series, NPort IA5000A-I/O Series, NPort IAW5000A-I/O Series, MiiNePort E1 Series, MiiNePort E2 Series, MiiNePort E3 Series, NPort S000 Series, NPort S9450I Series, NPort S9650I Series, NPort W2150A/W2250A Series, OnCell G3100-HSPA Series, OnCell G3101/G3201 Series, OnCell G3150A-LTE Series, OnCell G3470A-LTE Series, WE-2100T, CN2510 Series, CN2600 Series, NPort 5200 Series, NPort 5400 Series, NPort 5600 Series, NPort 5600-DT Series, NPort 6400/6600 Series, OnCell G3101-HSPA Series, NPort 5100 Series

Supported Operating Systems

Windows 10, Windows 7, Windows 8, Windows 8.1, Windows Server 2008 R2, Windows Server 2012 R2, Windows Server 2016, Windows Server 2019

New Features

- Supports Windows Server 2019.
- Supports VMware ESXi v6.7.0 for the following OSes: Windows 7 x86, Windows 8 x86, Windows 8.1 x64, Windows Server 2016, Windows 10 x64, Windows Server 2019

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A



Version: v3.0	Build: N/A
Release Date: Aug 23, 2018	

Applicable Products

N/A

Supported Operating Systems

Windows 10, Windows 7, Windows 8, Windows 8.1, Windows Server 2008 R2, Windows Server 2012, Windows Server 2012 R2, Windows Server 2016

New Features

N/A

Enhancements

Upgraded OpenSSL Library.

Bugs Fixed

- Fixed the network timeout issue in NPort Windows Driver Manager.
- When using the NPort 6000 in high security mode in Windows 10, may not be able to open ports.
- TCP port 60950 and 60966 are occupied even when not in use.
- Fixed BSOD which occurs when driver cancels pending IRPs.

Changes

Divided driver into separate versions, v3.0 supports Windows 7/8/8.1/10 and Windows Server 2008 R2/2012/2012R2.

Notes

This version is divided into two separate drivers (v2.0 and v3.0) to support different Windows platforms.