

Software Name: Firmware for NPort 6400/6600 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
1.17	N/A	null	N/A	New Features: <ol style="list-style-type: none">1. Supports new Micron flash due to component end-of-life.2. Supports 12-byte serial numbers.3. Supports the RTC RX8130CE chip. Enhancements: <ol style="list-style-type: none">1. Disabled TCP port 14900.2. Upgraded Dropbear SSH to 2017.75.3. Updated openssl library to 1.0.2k.4. Serial and Web console can use an empty pre-shared key to export plaintext config files.5. Radius and Tacacs+ can use attributes to manage user group policy.	Bugs Fixed: <ol style="list-style-type: none">1. NPort may reboot when opening port twice in Reverse RealCOM mode with secure enabled.2. Failing to modify serial settings through a telnet/ssh console.3. Failing to set the prefix netmask of the accessible IP list.4. System might restart with SNMP walk. Changes: N/A	N/A