

Software Name: Firmware for CN2600 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
3.1	N/A	null	N/A	<p>New Features: Supports Redundant COM function for CN2610-8/16.</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. RIP packets can't be sent via PPP & SLIP 2. AsyncServer's DHCP only sends a DHCP request twice. We modified the DHCP behavior; AsyncServer will continue to send DHCP discover packets if there is no DHCP response. 3. AsyncServer won't save the sender's MAC address if the target IP is not the IP of the CN2600. <p>Changes: N/A</p>	N/A