



Firmware for UC-8200 Series Release Notes

Version: v1.3	Build: 20072413
Release Date: Nov 26, 2020	

Applicable Products

UC-8200 Series

Supported Operating Systems

Moxa Industrial Linux (Debian 9)

New Features

N/A

Enhancements

N/A

Bugs Fixed

- Connection compatibility issue between the Moxa cell_mgmt utility and Verizon on u-blox's latest revision of TOBY-L201 for the Americas (model: TOBY-L201-02S-01).

Changes

N/A

Notes

N/A



Version: v1.2	Build: 20060314
Release Date: Jul 16, 2020	

Applicable Products

UC-8200 Series

Supported Operating Systems

Moxa Industrial Linux (Debian 9)

New Features

N/A

Enhancements

N/A

Bugs Fixed

- Fixed an issue wherein the Wi-Fi accessory driver sometimes fails to initialize.
- Reset to default does not reset the OS kernel.
- The hardware initialization default state of the DO is ON when booting into the OS; should be OFF. DO state OFF is equivalent to setting a value HIGH in the mx_dout_set_state() API of the Moxa DIO control library.

Changes

N/A

Notes

N/A



Version: v1.1	Build: N/A
Release Date: Jan 06, 2020	

Applicable Products

UC-8210-T-LX, UC-8220-T-LX-US-S, UC-8210-T-LX-S, UC-8220-T-LX-EU-S, UC-8220-T-LX-AP-S, UC-8220-T-LX

Supported Operating Systems

Debian 9.x

New Features

- First release.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A